INSPECTION REPORT

Partial Complete XXX Exploration Inspection Date: 08/22/2003/ Time: 9:00 – 12:00
Date of Last Inspection: 07/30/2003

Mine Name: <u>Centennial Project</u>	County: Carbon	Permit Number: <u>C/007/019</u>						
Permittee and/or Operator's Name: Andalex Resource, Inc.								
Business Address: P.O. Box 902, Price, Uta	ıh 84501							
Company Official(s): Mike Glasson								
State Official(s): Karl R. Houskeeper	Fede	ral Official(s): None						
Weather Conditions: Partly Cloudy, Temp 73° F, (Recent Storm Events)								
Type of Mining Activity: Underground XX	XX Surface Prep	PlantOther						
Existing Acreage: Permitted 5419.49 Dis	turbed 35.27 Re	graded Seeded Seeded						
Status: Active								

REVIEW OF PERMIT, PERFORMANCE STANDARDS & PERMIT CONDITION REQUIREMENTS

- 1. Substantiate the elements on this inspection by checking the appropriate performance standard.
 - a. For <u>complete inspections</u> provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check N/A.
 - b. For <u>partial inspections</u> check only the elements evaluated.
- 2. Document any noncompliance situation by referencing the NOV issued at the appropriate performance standard listed below.
- 3. Reference any narratives written in conjunction with this inspection at the appropriate performance standard listed below.
- 4. Provide a brief status report for all pending enforcement actions, permit conditions, Division Orders, and amendments.

		EVALUATED	N/A	COMMENTS	NOV/ENF
1.	PERMITS, CHANGE, TRANSFER, RENEWAL, SALE	[X]	[]	[X]	[]
2.	SIGNS AND MARKERS	[X]		<u>[X]</u>	口
3.	TOPSOIL	<u>[X]</u>	ΞĪ	ΞĪ	
4.	HYDROLOGIC BALANCE:				
a.	DIVERSIONS	[X]		[X]	\Box
b.	SEDIMENT PONDS AND IMPOUNDMENTS	[X]		[X]	
c.	OTHER SEDIMENT CONTROL MEASURES	[X]		[X]	
d.	WATER MONITORING	[X]	\Box	[X]	\Box
e.	EFFLUENT LIMITATIONS	[X]			
5.	EXPLOSIVES	[X]			
6.	DISPOSAL OF EXCESS SPOIL/FILLS/BENCHES	[X]			
7.	COAL MINE WASTE/REFUSE PILES/IMPOUNDMENTS		[X]		
8.	NONCOAL WASTE	<u>[X]</u>			
9.	PROTECTION OF FISH, WILDLIFE AND RELATED				
	ENVIRONMENTAL ISSUES	<u>[X]</u>			
10.	SLIDES AND OTHER DAMAGE	<u>[X]</u>			
11.	CONTEMPORANEOUS RECLAMATION	[X]	\Box		
12.	BACKFILLING AND GRADING	[X]			
13.	REVEGETATION	[X]			
14.	SUBSIDENCE CONTROL	[X]	\Box	[X]	
15.	CESSATION OF OPERATIONS	[X]			
16.	ROADS:				
a.	CONSTRUCTION/MAINTENANCE/SURFACING	[X]			
b.	DRAINAGE CONTROLS	[X]			
17.	OTHER TRANSPORTATION FACILITIES	[X]			
18.	SUPPORT FACILITIES/UTILITY INSTALLATIONS	[X]			
19.	AVS CHECK (4 th Quarter- April, May, June)	[X]			
20.	AIR QUALITY PERMIT	[X]		[X]	
21.	BONDING & INSURANCE	[X]		[X]	

INSPECTION REPORT

(Continuation Sheet)

PERMIT NUMBER: <u>C/007/019</u> DATE OF INSPECTION: <u>08/22/2003</u>

(COMMENTS ARE NUMBERED TO CORRESPOND WITH TOPICS LISTED ABOVE)

1. PERMITS, CHANGE, TRANSFER, RENEWAL, SALE

The current DOGM permit was re-issued effective 05/24/2002, to include the Mathis Tract, and expires 01/06/2007.

- -Certificate of Insurance issued 07/01/2003 and terminates 07/01/2004.
- -Reclamation agreement dated and signed February 1990 (amended January 2001).
- -UPDES permit UTG040008 effective 05/01/2003 and expires midnight 04/30/2008.
- -Air Quality permit DAQE-997-96, issued October 25, 1996.
- -SPCC Plan dated 12/05/2002.

2. SIGNS AND MARKERS

The mine permit ID sign located at the contact point of the public access to the permit area contained the required information. Other signs and markers observed during the inspection met the coal rules.

Topsoil sign has been re-posted adjacent to the topsoil pile in the left fork.

4A. HYDROLOGIC BALANCE: DIVERSIONS

The mine site has received several storms with the last week. Maintenance work on the diversion channels and culverts has been done to maintain compliance with the approved designs.

Several diversions were inspected during the inspection and were compliant with the designs in the approved MRP.

4B. HYDROLOGIC BALANCE: SEDIMENT PONDS AND IMPOUNDMENTS

Maintenance work has been done on the sediment retention basins since the recent storms. The dikes between the cells of the sediment basin have been reworked with drain rock.

Water is still present in the sediment catch basin and the sediment pond.

4C. HYDROLOGIC BALANCE: OTHER SEDIMENT CONTROL MEASURES

Several Silt Fence structures along the access road to the fan in the left fork need maintenance. The recent storm events have either placed material against the structures, under cut the structures, or side cut the structures.

The Silt Fence structures as a whole endured the high intensity storms and functioned as designed.

INSPECTION REPORT

(Continuation Sheet)

PERMIT NUMBER: <u>C/007/019</u> DATE OF INSPECTION: <u>08/22/2003</u>

4D. HYDROLOGIC BALANCE: WATER MONITORING

Second quarter 2003 water quality information is in the EDI pipeline. This information still needs to be approved and uploaded. Water monitoring is current.

14. SUBSIDENCE CONTROL

A letter dated October 2, 2002 from Bruce Ware indicates no change in subsidence monitoring from the previous year.

20. AIR QUALITY PERMIT

The air quality permit DAQE-997-96 referenced above remains in effect.

21. BONDING AND INSURANCE

The insurance referenced in item #1 above is through Federal Insurance Company, policy #37102594. The insurance has explosion coverage, meets the minimum coverage requirements, lists the Division as the certificate holder, and has the proper language on the notification policy.

Bond No. SU34593 is for \$381,839 and Bond No.SU1354086 is for \$699,000. Both bonds remain in effect for the term of the permit and are through Utica Mutual Insurance Company.

Inspector's Signature:			Date:	August 22, 2003
	Karl R. Houskeeper	#49		

Note: This inspection report does not constitute an affidavit of compliance with the regulatory program of the Division of Oil, Gas & Mining.

cc: James Fulton, OSM
Mike Glasson, Andalex, via email
Price Field office
O:\007019.CEN\Compliance\2003\C_0822.doc